
Software Release Notes

Software Details:

Chassis: **SL7xx**

Main software version: **os7.3**

M0906

→ SL7 UHD models with 0000 hardware

bild i.65 65A81FEVS

bild i.55 55A81FEVS

bild i.48 48A81FEVS

bild c.43 43A72FEVS

We.SEE 55 55A71FEVS

We.SEE 50 50A71FEVS

We.SEE 43 43A71FEVS

M0913

→ SL7 LCD UHD models with 0002 hardware

bild c.43 43A72FEVS(0002)

We.SEE 43 43A71FEVS(0002)

We.SEE 50 50A71FEVS(0002)

We.SEE 55 55A71FEVS(0002)

M0915

→ SL7 FHD models:

bild c.32: 32A72FEVS

32A71FEVS(0002)

We.SEE 32: 32A71FEVS

32A72FEVS(0002)

FRC software version: bild i.48: 28838

bild i.55: 28839

bild i.65: 28295

Release date: 20.09.2022

LOEWE.

New features:

ID	Title
LBH-424	Controlled Audio-Out (e.g. to connect Loewe klang sub1)
LBH-272	bild c.32/We SEE 32: Support of pictures with resolution higher than 1920x1080
LBH-423	HD+ App integrated (UHD TV models only)
LBH-311	Digit keys are now forwarded via HDMI-CEC
LBH-125	Volume/mute control via HDMI-CEC (e.g. from AppleTV) integrated
LBH-316	Unicable: Support of LNB frequency 10200MHz
---	Frequencies for satellite auto detection updated
---	Popup message added when connecting to unsecure networks
---	Pin added for reset to factory default
LBH-147	Integration of an API for home automation systems
---	Removed "Alphonso Enhanced Viewing"
LBH-269	Store Mode: Default volume is now 0
LBH-105	Store Mode: Function "Delete built-in video" added
LBH-92	Nordic countries: Fast scan for DVB-S operator "Allente - Thor 1°W" added
LBH-427	Nordic countries: Fast scan for DVB-C operator "Wao" added
LBH-347	Belgium: HbbTV activated
LBH-426	Switzerland: DVB-T enabled
LBH-176 LBH-425	When TV is switched off while active recording, the dialogue for standby recording is closed automatically after 15 seconds

Optimizations:

ID	Title
LBH-247	Correction of a problem where sometimes no sound was available via HDMI-ARC after switch-on
LBH-268	Amplifiers (connected via HDMI-ARC) are not switched on now while standby-recordings are executed
LBH-174	No endless recording is done anymore when recording is started from timeshift mode
LBH-275	Correction of a problem where TV switched off after 20 minutes in "Audio only" mode and while usage of Bluetooth music player

LOEWE.

ID	Title
LBH-317	Menu "Format Hard Disk" removed for TV models without integrated hard disk
LBH-372	Fixed a problem that caused glitches and stuttering when playing back videos from Disney+ and Netflix via AppleTV
LBH-429	Nordic countries: Fixed a problem where no audio/video was available after recording in standby
---	Further bug fixes

Previous versions:

os7.2-M0411 (UHD devices) / M0412 (FHD devices)

New features:

ID	Title
LBH-188	Recording/timeshift enabled for Nordic countries
---	New search mode "Quick Scan" for DVB-S standard search
LBH-89	New screen saver for OLED devices
LBH-141	Preparation for upcoming native apps Disney+, Apple TV+

Optimizations:

ID	Title
LBH-365 LBH-364 LBH-289 LBH-275	bild i: Correction of a problem where the TV set switches off automatically in timeshift mode, during music playback or in "audio only" mode.
LBH-315	bild c.32/We. SEE 32: Correction of a problem in Italy where the TV occasionally starts without video
LBH-369	bild c.32/We. SEE 32: Fixing an issue where Alexa setup fails in the UK
---	Optimisation of DVB-T search in Germany
LBH-308	Fixing an issue where DVB channels were blocked by parental controls for ages 19+ (e.g. TV5MONDE)
LBH-279	Correction of a problem where a WLAN access point cannot be connected with activated fast roaming
LBH-304	Fixing an issue where the playback of a recording of a free channel is blocked due to an invalid expiry time
---	Sky Q Box: Fixing an issue where a black screen appears with a 4K Netflix video
LBH-314	Sky Q Box: Fixing picture and sound dropouts during a live UHD broadcast
---	Fix for an issue where the TV screen is blurry when Xbox is connected in game mode or ALLM
---	Corrected mapping between ALLM and game mode
---	Fixed an issue where the TV does not respond to the Vol+/- and Mute buttons when HDMI CEC is turned off

LOEWE.

ID	Title
LBH-313	Fixed an issue where the TV would lock up when opening jpg photos
LBH-265	Fixed an issue where logging into the VIDAA account fails if the email address contains a hyphen
LBH-367	Optimization of Dolby Atmos
---	Correction of some image parameters
LBH-127 LBH-131 LBH-132 LBH-162 LBH-182 LBH-219 LBH-262 LBH-293	Texts and translations corrected and improved

os7.1-L0902 (We. SEE 55), L0909 (bild i.48/55/65), L0910 (bild c.43, We. SEE 43), L0915 (We. SEE 50)

New features:

ID	Title
LBH-97	Integration of the Loewe switch-off curtain
---	Extension of the supported DVB networks (e.g. Ziggo, UPC, Vodafone, Calbe Ready, Telenor, ComHem, Stofa, YouSee)

Optimizations:

ID	Title
---	Improved control of the ambient light sensor
---	Optimisation of picture settings
LBH-137	Resolved an issue that caused missing sound during recordings and time-shifted playback
---	Improved lip sync when using Amazon Video
---	Fixing an issue with klang bar 5 mr that caused eARC to disable after standby

LOEWE.

ID	Title
LBH-256	Resolving a problem that caused blocking and crashes when switching during regional time windows
LBH-136	Correction of a bug that caused the TV to switch off after 20 minutes in radio mode
---	Correction of an issue where Alphonso Enhanced Viewing would automatically start Timeshift when a sporting event was detected
---	Bug fixes related to Vodafone CAMs
---	Translation of terms and conditions and privacy policy
---	UI optimisations